



**GOVERNMENT OF ODISHA  
DEPARTMENT OF WATER RESOURCES**

**PURI IRRIGATION DIVISION PURI**

**Health Status of embankment under Puri Irrigation  
Division, Puri for the year 2021 duly signed by Collector  
and District Magistrate, Puri**

Date:- April 2021

Executive Engineer,  
Puri Irrigation Division, Puri


**Collector & District Magistrate, Puri**


Sir,

Circular No. - 11494/dated 7.4.2021 of E.I.C, Water Resources, Odisha, Bhubaneswar regarding checking of health status of river and saline embankments by joint inspection of Tahasildar / B.D.Os/ P.R.I members and the concerned field Engineers to be completed by 16.4.2021 may kindly be perused.

A tentative schedule of verification by the Tahasildars / Block Development Officers and the concerned field Engineers has been prepared from 16.4.2021 to 26.4.2021 which may kindly be approved.

OK.

  
12/4/21  
Collector, Puri

  
12/4/2021  
Executive Engineer,  
Puri Irrigation Division, puri  
12/4/21


**Collector & District Magistrate, Puri**


Sir,

As per order of your good self, the joint inspection to the river embankment s were made by concerned Tahasildars/ Addl. Tahasildars/ BDO's/ PRI Members alongwith field Engineers of Puri Irrigation Division, Puri from dated 16.4.2021 to 26.4.2021.

The health status of embankments is mentioned against each date of joint inspection by the aforesaid officers. The consolidated reports for all the embankments jointly inspected are prepared which may kindly be approved at your end for onward transmission to Govt.

Put up for approval

  
Executive Engineer,  
Puri Irrigation Division, Puri

  
Collector & District Magistrate,  
Puri  
~~Collector & Dist Magistrate~~  
Puri

**STATUS OF CAPITAL EMBANKMENT , OAE, TRE,SALINE EMBANKMENT IN PURI AND KHORDHA DISTRICT  
UNDER PURI IRRIGATION DIVISION,PURI**

Sl. No.	Name of District	Type and length of embankment in km				
		Capital	OAE	TRE	SE	TOTAL
1	2	3	4	5	6	8
1	Puri	283.20	117.10	130.85	384.49	915.64
2	Khordha	10.10				10.10
		<b>293.30</b>	<b>117.10</b>	<b>130.85</b>	<b>384.49</b>	<b>925.74</b>
* Apart from that this Division have maintained 23.85 kms of Gherry bundha.						<b>23.85</b>
<b>G.Total</b>						<b>949.59</b>



Executive Engineer,  
Puri Irrigation Division,Puri

**STATUS REPORT OF EMBANKMENT UNDER O/O THE EXECUTIVE ENGINEER, PURI IRRIGATION DIVISION, PURI**

Sl. No.	Name of the embankment	Joint verification by the Officer concerned	Date of inspection	Remarks
1	2	3	4	5
1	Bhargavi right embankment from RD 0.00 km to 24.00 km ( from village Uttara to Maujabeg)	Sri Sapan Kumar Nanda, OAS, Tahasildar, Pipili , Sri Jitendra Kumar Panda , OAS, Addl. Tahasildar, Pipili , Sri Tapan kumar Majumdar, AEE, Pipili Irrigation Sub-Division, Pipili (I/C) , Sri Jitu Krishna Nanda, AE, Uttara Irrigation Section, Uttara, Sri Ramakanta Parija, AE, Dandamukundapur Irrigation Section, Sri Madhab Chandra Sarangi, AE, Satasankha Irrigation Section,	20.4.2021	The embankment is in good condition and there is no danger to sustain flood during monsoon period. However watch and ward is necessary during flood period.
2	Daya left embankment from RD 0.00 km to 24.00 km ( From village Uttara to Neempur)	Sri Sapan Kumar Nanda, OAS, Tahasildar, Pipili , Sri Jitendra Kumar Panda , OAS, Addl. Tahasildar, Pipili , Sri Tapan kumar Majumdar, AEE, Pipili Irrigation Sub-Division, Pipili (I/C) ,Sri Himansyu Sekhar Mandhata, JE, Pipili HQ section, Pipili, Sri Madhab Chandra Sarangi, AE, Kanti Irrigation Section,	23.4.2021	The embankment is in good condition and there is no apprehension for ensuing flood 2021
3	Bhargavi right embankment from RD 24.00 km to 48.00 km	Sri Manoj Kumar Nayak, OAS, Tahasildar, Satyabadi tahasil, Sri Raghunath Swain, DEE, Sakhigopal Irrigation Sub-Division, Sri Suresh Kumar Sahoo, JE, Rupadeipur Irrigation Section, Sri Adhikari Mrutyunjaya Dash, AE, HQ, Sakhigopal	22.4.2021	The embankment is in good condition. However watch and ward during flood period is necessary.
4	Bhargavi right embankment from RD 48.00 km to 87.500 km	Smt. Mili Behera, Jillaparisad Member, 30 No. Zone , Brahmagiri, Sri Raghunath Swain, DEE, Sakhigopal Irrigation Sub-Division, Sri kalu Charan Palei, AE, Rahadamal Irrigation Section,	22.4.2021	The embankment is in good condition. However watch and ward during flood period is necessary.

Sl. No.	Name of the embankment	Joint verification by the Officer concerned	Date of inspection	Remarks
1	2	3	4	5
5	Daya left embankment from RD 24.500 km to 38.800 km , (from village Neepur to Haladiapadar) Luna left embankment from RD 0.00 km to 16.500 km ( from village Hata Delang to Andalasingh) and Luna right embankment from RD 0.00 km to 4.00 km	Sri Ranjan Kumar Nayak, OAS, Addl. Tahasildar, Delang Tahasil, Sri Naba Kishore Mohapatra, AEE, Delang Irrigation Sub-Division, Sri tanuj Kishore Rout, AE, Delang Irrigation Section, Delang, Sri Makar Behera, AE, Kanas Irrigation Section, Kanas	23.4.2021	The embankment is in good condition and there is no apprehension for ensuing flood 2021
6	Daya left embankment from RD 38.800 km to 60.00 km and Luna right embankment from RD 4.00 km to 26.00 km ( from village kalyanpur to Nuagaon)	Sri Laxmidhar Moharana, OAS, Tahasildar, Kanas Tahasil, Sri Naba Kishore Mohapatra, AEE, Delang Irrigation Sub-Division, Sri Makar Behera, AE, Kanas Irrigation Section, Kanas	23.4.2021	The embankment is in good condition and there is no apprehension for ensuing flood 2021
7	Bhargavi left embankment from RD 37.00 km to 56.00 km	Sri Parsuram Mallick, OAS, Addl. Tahasildar, Puri Sadar , Sri Tapan Kumar Majumdar, AEE, Puri Irrigation Sub-Division, Puri , Sri Himansyu Sekhar Mandhata, JE, Chandanpur (I/C)	23.4.2021	The embankment is in good condition and appear to be withstanding the flood pressure. However properly watch and waod required during flood.
8	Bhargavi left embankment from RD 56.00 km to 75.00 km (From village Kamasasan to Srikata Nuapada)	Sri Jyoti Prakash Sethi, BDO, Brahmagiri Block, Sri Sadanan Pradhan, A,E, Headquarter Section-II,Puri	20.4.2021	The embankment is in good condition and there is no apprehension for ensuing flood 2021
9	Bhargavi left embankment from RD 75.00 km to 85.00 km	Sri Purna Chandra Sethi, OAS, Addl. Block Development Officer, Brahmagiri Block, Sri Tapan Kumar Majumdar, AEE, Puri Irrigation Sub-Division, Puri , Sri Susanta Kumar Dora, A,E, Sunamuhin Irrigation Section	22.4.2021	The embankment is in good condition and there is no apprehension for ensuing flood 2021

Sl. No.	Name of the embankment	Joint verification by the Officer concerned	Date of inspection	Remarks
1	2	3	4	5
10	Gabakund Cut right embankment from RD 0.00 km to 11.66 km and left embankment from RD 0.00 km to 11.66 km ( Puri-Konark road, madhipur chhak to Dhola)	Sri Parsuram Mallick, OAS, Addl. Tahasildar, Puri Sadar , Sri Tapan Kumar Majumdar, AEE, Puri Irrigation Sub-Division, Puri , Sri Himansyu Sekhar Mandhata, JE, Incharge of Gabkund	23.4.2021	The embankment is in good condition and appear to be withstanding the flood pressure. However properly watch and ward required during flood.
11	Bhargavi- Ratnachira right embankment from RD 0.00 km to 10.00 km ( from village Pratapramachandrapur to khajuria)	Smt. Sita Pradhan, Sarapanch, Goudakera, Sri Raghunath Swain, DEE, Sakhigopal Irrigation Sub-Division, Sri Prabhat Kumar hota, A.E, P.R. Puri Irrigation Section,	22.4.2021	The embankment is in good condition. However watch and ward during flood period is necessary.

12/5/2021  
Executive Engineer,  
Puri Irrigation Division, Puri

7/5/2021  
Superintending Engineer,  
Central Irrigation Circle, Bhubaneswar  
Bhubaneswar-12

Collector & District Magistrate,  
Puri  
**Collector & Dist. Magistrate**  
Puri

Joint Verification of River Embankment under Pipili Irrigation Sub Division.

On 20.04.2021 a joint verification has been conducted by the following Officers Of Puri District Administration and Pipili Irrigation Sub Division under Puri Irrigation Division for inspection of river embankment for the year 2021.

1. Sapan Kumar Nanda OAS Tahasildar, Pipili Tahasil.
2. ~~Jitendra~~ Kumar Panda OAS Addl. Tahasildar Pipili Tahasil.
3. Tapan kumar Majumdar Asst. Executive Engineer, Pipili Irrigation Sub Division
4. Jitu Krushna Nanda Asst Engineer, Uttara Irrigation Section.
5. Rama Kanta Parija Asst Engineer, Dandamukundapur Irrigation Section
6. Madhab Chandra Sarangi Asst Engineer, Satasankha Irrigation Section

Inspected Bhargavi River Right Embankment from RD 00 to 24.00km ( from village Uttara to maujabeg). The entire embankment is in good condition and appears to be withstanding the flood pressure. There is no apprehension for the ensuing flood in the year 2021.

  
20/4/21  
Asst Engineer

Uttara .Section

  
20/4/21  
Asst Engineer

D.M.Pur Section

  
20/4/2021  
Asst Engineer


Satasankha .Section, Pipili Irr Sub Division

  
20/4/21  
Asst Executive Engineer

Pipili Irr Sub Division

  
20/4/21  
Addl. Tahasildar

Pipili Tahasil.

  
20/4/21  
Tahasildar

Pipili Tahasil.




Joint Verification of River Embankment under Pipili Irrigation Sub Division.


On 23.04.2021 a joint verification has been conducted by the following Officers Of Puri District Administration and Pipili Irrigation Sub Division under Puri Irrigation Division for inspection of river embankment for the year 2021.


1. Sapan Kumar Nanda OAS Tahasildar, Pipili Tahasil.
2. ~~Jitendra~~ Kumar Panda OAS Addl. Tahasildar Pipili Tahasil.
3. Tapan kumar Majumdar Asst. Executive Engineer , Pipili Irrigation Sub Division
4. Himanshu Sekhar Mandhata Junior Engineer, Pipili H.Q. Irrigation Section.
5. Madhab Chandra Sarangi Asst Engineer , Kanti Irrigation Section


Inspected Daya River Left Embankment from RD 00 to 24.00km ( from village Uttara to Neempur). The entire embankment is in good condition and appears to be withstanding the flood pressure. There is no apprehension for the ensuing flood in the year 2021.

  
23/4/2021  
Junior Engineer  
Pipili H.Q. Irr. Section

  
23/4/2021  
Asst Engineer  
Kanti Irr .Section,


  
23/4/21  
Asst Executive Engineer  
Pipili Irr Sub Division


  
23/4/21  
Addl. Tahasildar  
Pipili Tahasil.


  
23/4/21  
Tahasildar  
Pipili Tahasil.


**JOINT VERIFICATION OF BHARGAVI RIGHT EMBANKMENT FROM RD 24.00KM TO 48.00KM OF SAKHIGOPAL IRRIGATION SUB-DIVISION UNDER PURI IRRIGATION DIVISION, PURI.**

Jointly inspected Bhargavi Right embankment from RD 24.00km to 48.00km on dt.22.04.2021. It is seen that the embankment is in good condition. However watch & ward during flood period is necessary. Also instructed to keep sand bags for flood protection at the time of high flood.

  
Asst. Engineer  
Rupadeipur Irr. Sec.


  
Asst. Engineer  
Skgl. (Hq.) Irr. Sec.

  
Deputy Executive Engineer,  
Sakhigopal Irr. Sub-Divn.

  
Tahasildar,  
Satyabadi.


Memo No. 325 //Dated. 22.4.2021.//

Copy submitted to the Collector, Puri for favour of information & necessary action.

  
Tahasildar,  
Satyabadi.

Memo No. 326 //Dated. 22.4.2021.//

Copy submitted to the Executive Engineer, Puri Irrigation Division, Puri for favour of information & necessary action.

  
Tahasildar,  
Satyabadi.

**JOINT VERIFICATION OF BHARGAVI RIGHT EMBANKMENT FROM RD 48.00KM TO 87.500KM OF SAKHIGOPAL IRRIGATION SUB-DIVISION UNDER PURI IRRIGATION DIVISION, PURI.**

Jointly inspected Bhargavi Right embankment from RD 48.00km to 87.500km on dt.22.04.2021. It is seen that the embankment is in good condition. However watch & ward during flood period is necessary. Also instructed to keep sand bags for flood protection at the time of high flood.

*File*  
*22/04/2021*  
Asst. Engineer  
Rahadmal Irr. Sec.

*[Signature]*  
Deputy Executive Engineer,  
Sakhigopal Irr. Sub-Divn.


*Mimi Behena*  
Zillaparisad Member  
30 No. Zone, Brahmagiri  
22.4.2021  
Zillaparisad  
Brahmagiri Zone No.


# JOINT VERIFICATION OF BHARGABI RATNACHIRA RIGHT EMBANKMENT.


## Name of the officers present.

1. Sita Pradhan, Sarpanch, Gaudakera.
2. Er. Raghunatha Swain, Deputy Executive Engineer, Sakhigopal Irrigation Sub-Division, Sakhigopal.
3. Pravat Kumar Hota, Assistant Engineer, Pratapramachandrapur Irrigation Section.

Inspected Bhargabi Ratnachira Right Embankment from RD. 00 km to 10.00 km i.e. Pratapramachandrapur to Khajuria on Dated.22.04.2021. The whole embankment is in good condition. However watch and ward during flood period in necessary and also instructed to keep flood fighting materials like sand bags, bamboo during high flood.

  
Assistant Engineer,  
P.R. Pur Irrigation Section

  
Deputy Executive Engineer,  
Sakhigopal Irrigation Sub-Division,  
Sakhigopal


  
Sarpanch  
Gaudakera G.P.


JOINT VERIFICATION OF RIVER EMBANKMENT ON 23.04.2021


On dated 23.04.2021 a joint inspection has been conducted by the following officers of Puri District administration and Puri Irrigation Division for inspection of river embankment of Delang Irrigation Sub-Division for the year 2021

1. Sri Ranjan Kumar Nayak, Additional Tahasildar, Delang Tahasil
2. Naba Kishore Mohapatra, Assistant Executive Engineer, Delang Irrigation Sub-Division
3. Tanuja Kishore Rout, Assistant Engineer, Delang Irrigation Section No-I
4. Makar Behera, Assistant Engineer, Ghoradia Irrigation Section.

Inspected Daya left embankment from Neepur to Haladipadar ( i.e RD from 24.500km to 38.800km  
The whole embankment is in good condition & appears to withstand the flood pressure. Also,  
inspected Luna left embankment from Hata Delang to Andalsingh ( i.e from RD 00 to 16.500km ) &  
Luna right embankment from RD 00 to 4.00km & found no such weak portion .The embankment is in  
good condition . There is no apprehension for the ensuing flood in the year 2021.

  
23/04/2021  
( Tanuja Kishore Rout )  
Assistant Engineer  
Delang Irrigation Section-I

  
23/04/2021  
(Naba Kishore Mohapatra).  
Assistant Executive Engineer  
Delang Irrigation Sub-Division

  
23/04/2021  
( Ranjan Kumar Nayak )  
Addl. Tahasildar  
Delang Tahasil




JOINT VERIFICATION OF RIVER EMBANKMENT ON 23.04.2021


On dated 23.04.2021 a joint inspection has been conducted by the following officers of Puri District administration and Puri Irrigation Division for inspection of river embankment of Delang Irrigation Sub-Division for the year 2021.


1. Sri Laxmidhar Moharana . Tahasildar, Kanas Tahasil
2. Naba Kishore Mohapatra, Assistant Executive Engineer, Delang Irrigation Sub-Division
3. Makar Behera, Assistant Engineer, Kanas Irrigation Section


Inspected Daya left embankment from Trilochanpur to Gadishagada ( i.e RD from 38.800km to 60.00km ) . The whole embankment is in good condition & appears to withstand the flood pressure. Also, inspected Luna right embankment from Kalyanpur to Nuagaon ( i.e from RD 4.00 to 26.00km ) & found no such weak portion . The embankment is in good condition . There is no apprehension for the ensuing flood in the year 2021.

Makar  
23-4-2021  
( Makar Behera )  
Assistant Engineer  
Kanas Irrigation Section ..

  
(Naba Kishore Mohapatra)  
Assistant Executive Engineer  
Delang Irrigation Sub-Division

  
( Laxmidhar Moharana )  
Tahasildar  
Kanas Tahasil

  
23/4/21


  
23/4/21

## JOINT VERIFICATION OF BHARGAVI LEFT EMBANKMENT


### Name of the officers present

- 1 Jyoti Prakash Sethy BDO, Brahmagiri Branch
- 2 Sadanana Pradhan, Assistant Engineer, Puri Head Quarter Section,

Inspected Bhargavi left embankment from RD 56.00 km to 75.00 km ie from Kamasasan to Srikata Nuapada Sluice on Dt. 20.04.2021. The whole embankment is in good condition. However watch and ward during flood period is necessary and also instructed to keep flood fighting materials like sand bags, bamboo during high flood.

  
Assistant Engineer  
Puri HQ Section, Puri

  
Deputy Executive Engineer  
Puri Irrigation Sub-Division, Puri


  
Block Development Officer  
Brahmagiri


JOINT VERIFICATION OF BHARGAVI LEFT EMBANKMENT

Name of the Officer present

1. Sri puurna ch. Setty. ABDO, Bhahangini
2. Sri Susanta Kumar Dora, Assistant Engineer, Sunamuhin Irrigation Section.
3. Sri Tapan Kumar Majmudar, Assistant Executive Engineer, Puri Irrigation Sub-Division, Puri.

Inspected Bhargavi left embankment from RD. 75.00 km. to 85.00 km. ie Village Nuapada to Talakokala on dated 22.04.2021. The whole embankment is in good condition. However watch and ward during flood period is necessary and also inspected to keep flood fighting material like sand bags, sand, bamboo during high flood.

  
22.04.2021  
Assistant Engineer  
Sunamuhin Irrigation Section  
Sunamuhin

  
22/04/2021  
Assistant Executive Engineer  
Puri Irrigation Sub-Division  
Puri

  
22.04.21  
BLOCK DEVELOPMENT OFFICER  
Brahmagiri



JOINT VERIFICATION OF RIVER EMBANKMENT

Date of inspection:- Dt. 23.4.2021

Name of the Officers Present:-

1. Persuram Malik-OAS-Addl. Tahasildar, Puri
2. Tapan Kumar majumdar, AEE, sdo, Puri Irrigation Sub-division, Puri
3. Himansu Sekhar Mandhata, J.E, Chandanpur and Gabkund

Inspected the following embankment: \_

- ✓ 1. Gobkund cut right embankment RD 0.00 km 11.66 km

❖ The complete length is in good condition and appears to be withstanding the flood pressure.


- ✓ 2. Gobkund cut left embankment from RD 0.00 km to 11.66 km ( Puri- Konark road (Mohinpur Chhak to Dhola)


❖ The complete length is in good condition. The vulnerable point near village Jamarasuan has restored and appears to be withstanding the flood pressure.


- ✓ 3. Bhargavi left embankment from RD 35.00 km to 56.00 km ( village Dhol to Dobandha via Chandanpur) upto Chandanpur Ntt.

❖ The complete length is in good condition and appears to be withstanding the flood pressure.

However properly watch and ward required during the flood. There is no apprehension for the ensuing flood in the year 2021.

  
23/4/21  
Er. Himansu Sekhar Mandhata  
Junior Engineer  
Chandanpur/ Gabkund

  
23/4/21  
Er. Tapan Kumar Majumdar,  
Assistant Executive Engineer,  
Puri Irrigation Sub-Division, Puri

  
23/04/2021  
Sri Persuram Malik, OAS  
Addl. Tahasildar  
Purisadar Tahasil, Puri