

**Embankment Inspection of Nuapada Irrigation Division, Date:-19.05.2020 as per EE, Nuapada Irrigation Division  
913, (WE), (3), dtd-15.05.2020.**

**Lr. No:-**

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	Kokrijhore Nallah	Bargarh	Jharbandh	Padmapur	Right (0.50Km)	Kotna embankment (Embankment near village Kotna in D/S of Spillway of Jharbandh Irrigation Project.	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.
2	Mahanadi	Ong River	Bargarh	Jharbandh	Padmapur	Left (0.70Km)	Lergaon embankment (Embankment of river Ong near village Lergaon)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
19/05/2020  
Junior Engineer  
Jharbandh Irrigation Sub-Division  
Jharbandh

*[Signature]*  
19/05/2020  
Sub-Divisional Officer  
Jharbandh Irrigation Sub-Division  
Jharbandh

*[Signature]*  
Block Development Officer  
Jharbandh

*[Signature]*  
19/05/2020  
Executive Engineer  
Nuapada Irrigation Division  
Nuapada.

*[Signature]*  
19/05/20  
Sarapanch  
Kumir G.P.

*[Signature]*  
19.5.20  
Rasana Sahu  
P.S. Member  
Kumir G.P.

*[Signature]*  
19-05-2020  
PRESIDENT  
Mas Lergani Pani Panchayat  
At. Lergaon Po. Shabu

*[Signature]*  
19/05/20  
SECRETARY  
Mas Lergani Pani Panchayat  
At. Lergaon Po. Shabu

*[Signature]*  
19.5.20  
Revenue Supervisor  
Tahasil Office, Jharbandh

*[Signature]*  
19/05/2020  
Tahasildar  
Jharbandh

Countersigned  
*[Signature]*  
16/5/2020  
COLLECTOR  
BARGARH

Embankment Inspection of Nuapada Irrigation Division, Date:-18.05.2020 as pe EE, Nuapada Irrigation Division Lr. No:-913, (WE), (3), d  
15.05.2020.

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	(Un named Tributary of Ong) Dumerbahal Nallah	Bargarh	Paikmal	Padmapur	L/R	Bhutmunda embankment (Embankment near village bhutmunda in D/S of Spillway of Dumerbahal Irrigation Project.	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
18-05-2020

Asst. Engineer  
Mandosil Irrigation Sub-Division  
Mandosil.

*[Signature]*  
18/5/2020

Sub-Divisional Officer  
Mandosil Irrigation Sub-Division  
Mandosil  
**Deputy Executive Engineer  
Nuapada Irrigation Division**

*[Signature]*  
18/5/2020

Executive Engineer  
Nuapada Irrigation Division  
Nuapada.

*[Signature]*  
Revenue Inspector  
Mandosil  
**MANDOSIL**

*[Signature]*  
\* Sarpanch Mandosil G.P.

Sarpanch  
Mandosil G.P.

*[Signature]*  
Tahasil Paikmal  
**Tahasil Paikmal**

*[Signature]*

ସମିତି ସଭା  
ମାଣ୍ଡୋସିଲ ଗ୍ରାମ ପଂଚାୟତ

Countersigned.  
*[Signature]*  
18/5/2020

**COLLECTOR  
BARGARH**

*[Signature]*  
18/5/2020  
**B. D. O  
PAIKMAL**

**Embankment Inspection of Nuapada Irrigation Division, Date:-18.05.2020 as pe EE, Nuapada Irrigation Division Lr. No:-913, (WE), (3), dtd-15.05.2020.**

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	(Un named Tributary of Ong) Saipala Nallah	Nuapada / Bargarh	Nuapada / Paikmal	Nuapada / Padmapur	L/R	Pipalchhendei Embankment (Embankment near village Pipalchhendei in D/S of Spillway of Saipala Irrigation Project.)	After field visit by the team it is observed that the total existing river embankment is in good condition. In down stream of spillway at RD 680 m needs improvement.

*B. Singh*  
19/05/2020  
Junior Engineer  
Nuapada Irrigation Sub-Division  
Saipala Irrigation Sub-Division  
Nuapada  
Saipala.

*S. K. Saha*  
19/5/20  
Sub Divisional Officer  
Nuapada Irrigation Sub-Division  
Nuapada

*[Signature]*  
Executive Engineer  
Nuapada Irrigation Division  
Nuapada

*[Signature]*  
19/05/20  
Revenue Inspector  
Darlimunda

*[Signature]*  
19.05.2020  
B.D.O. Nuapada  
Block Development Officer  
NUAPADA

*[Signature]*  
Tahasildar, Nuapada

*Chandrasekar Tanti*

*[Signature]*  
B.D.O. Paikmal  
Block Development Officer  
Paikmal Block

*[Signature]*  
Tahasildar, Paikmal  
Tahasildar  
Paikmal

Sarpanch  
Saipala G.P.

*[Signature]*  
19/5/20  
Revenue Inspector  
Jamseth

Counter Signature

*[Signature]*  
28.5.20  
COLLECTOR  
NUAPADA

*[Signature]*  
Junior Engineer  
Nuapada Block

*Himadri Pata*  
Sarpanch  
Mandosil G.P.

**Embankment Inspection of Nuapada Irrigation Division, Date:-02.05.2019 as per Lr. No-12250, dt-26.04.2019 of Engineer-in-Chief, WR, Odisha, Bhubaneswar & EE, Nuapada Irrigation Division Lr. No-1223, (3), dtd-27.04.2019.**

Sl. No	Basin	River	District	Block	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	Un named Tributary of Ong	Nuapada	Nuapada	Nuapada	L/R	Pipalchhendi embankment (embankment near village Pipelchhendi in down stream of Spillway of Saipala Irrigation Projec.)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*Beghna*  
25/19  
Junior Engineer

*S.P. Ramesh*  
25/19  
Sub-Divisional Officer  
Nuapada Irrigation Sub-Division  
Nuapada.

*[Signature]*  
Executive Engineer  
Nuapada Irrigation Division  
Nuapada

*[Signature]*  
25/2019  
R.I. Darabimunda

Chandramoni Tanti  
Sarpanch  
Saipala G.P.

*[Signature]*  
ସମିତି ସଭ୍ୟ  
ସାଇପାଳା ଗ୍ରା. ପ.

*[Signature]*  
2.5.19.  
TAHASILDAR  
NUAPADA

*SP*  
2/5/19  
BLOCK DEVELOPMENT OFFICER  
NUAPADA

Counter Signature  
*[Signature]*  
COLLECTOR  
NUAPADA  
25/5/19

**Embankment Inspection of Nuapada Irrigation Division, Date:-01 & 02.05.2019 as per Lr. No-12250, dt-26.04.2019 of Engineer-in-Chief, WR, Odisha, Bhubaneswar & EE, Nuapada Irrigation Division Lr. No-1223, (3), dtd-27.04.2019.**

Sl. No	Basin	River	District	Block	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	Un named Tributary of Ong	Bargarh	Paikmal	Padmapur	L/R 0.80km Left.	Bhutmunda Embankment (Embankment near village Bhutmunda D/S of Spillway of Dumerbahal Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no such vulnerable point noticed.
2	Mahanadi	Ong	Bargarh	Jharbandh	Padampur	L/R 0.70km Left side of Ong.	Lergaon embankment (Embankment of river Ong near village Lergaon)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.
3	Mahanadi	Kakarjore nallah	Bargarh	Jharbandh	Padampur	L/R 0.50 At emb. of Kakarjore nallah.	Kotna embankment (Embankment near village Kotna in D/S of Spillway of Jharbandh Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no such vulnerable point noticed.

*[Signature]*  
2-05-19  
Junior Engineer

*[Signature]*  
Sub-Divisional Officer  
Mandosil Irr. Sub-Division  
Mandosil Irrigation S/Divn.  
Mandosil

*[Signature]*  
07.05.2019  
Sub-Divisional Officer  
Jharbandha Irr. Sub-Division  
Jharbandha.

Himachhi Peta  
Sarpanch  
Mandosil G.P.

*[Signature]*  
6/5/19  
Revenue Inspector  
MANDOSIL

*[Signature]*  
ସମିତି ସଭ୍ୟା  
ମାଣ୍ଡୋସିଲ ଗ୍ରାମ ପଂଚାୟତ

*[Signature]*  
7/5/19  
Revenue Inspector  
Jharbandh

*[Signature]*  
Executive Engineer  
Nuapada Irrigation Division  
Nuapada Irrigation Division  
Nuapada

*[Signature]*  
Tahsil Officer  
Jharbandh