

OFFICE OF THE SUPERINTENDING ENGINEER  
NUAPADA IRRIGATION DIVISION, NUAPADA  
Ph No-06678225434, e-mail:-ee.npd.irr@gmail.com

Letter No: - 1100/WE

Date:- 07/05/2022


To  
The Additional Chief Engineer,  
Western Irrigation Circle,  
Bhawanipatna.

Sub- Submission of information on embankment verification report of ensuing Flood-2022.

Sir,  
In inviting a kind reference to the above cited above, the information regarding embankment verification report of ensuing Flood-2022 in the prescribed proforma duly countersigned by the Collector, Nuapada & Collector, Bagarh is submitted herewith for favour of kind information and necessary action.

Encl:- As above.

Yours faithfully


  
7/5/22  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada

Memo No:- 1101/WE

Date:- 07/05/2022

Copy along with copy of enclosures submitted to the Chief Engineer & Basin Manager, Tel Basin, Bhawanipatna for favour of kind information and necessary action with reference to his memo No-598 dt-06.04.2022.

Encl:- As above.

  
7/5/22  
SUPERINTENDING ENGINEER.

*Every drop of water is precious.*  
Use optimally by adopting recycle, reuse and zero discharge technology.

**Embankment Inspection of Nuapada Irrigation Division, Date:-02.05.2022 to 05.05.2022 as per Superintending Engineer,  
Nuapada Irrigation Division Lr. No:-983, (WE), (3), dtd-25.04.2022.**

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation	Length of Embankment in Km
1	Mahanadi	Jonk	Nuapada	Nuapada/ Nuapada	Nuapada	L/R	Patora embankment near village Patora in D/S of the Spillway of Upper Jonk Irrigation Project.)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.8
2	Mahanadi	Jonk	Nuapada	Nuapada/ Nuapada	Nuapada	R	Kurumunda embankment (Embankment over Jonk river near village Kurumunda)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.9
3	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada/ Nuapada	Nuapada	L/R	Kalyanpur embankment (Embankment of Kharkhara Nallah near village Kalyanpur and U/S Kharkhara Barrage )	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.9
4	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada/ Nuapada	Nuapada	L/R	Mahatamora embankment (Embankment near village Mahatamora of Kharkhara Nallah)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.5



5	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada/ Nuapada	Nuapada	L	Chanabeda embankment (Embankment near village Chanabeda in D/S of Kharkhara Barrage)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.6
6	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada/ Nuapada	Nuapada	R	Silda embankment (Embankment near village Silda)	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.	0.2

*K. S. 4/5/2022*  
Assistant Engineer  
Jonk Irrigation Sub-Division  
Nuapada

*K. S. 5/5/22*  
Assistant Engineer  
Jonk Irrigation Sub-Division  
Nuapada

*K. S. 4/5/2022*  
Assistant Engineer  
Jonk Irrigation Sub-Division  
Nuapada

*K. S. 4/5/22*  
Tahasildar  
Nuapada

*K. S. 5/5/2022*  
Sub-Divisional Officer  
Jonk Irrigation Sub-Division  
Nuapada.

*K. S. 5/5/22*  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada.

*K. S. 5/5/22*  
Inspector  
Charit-Koad

*K. S. 5/5/22*  
Inspector  
Charit-Koad

*K. S. 5/5/2022*  
Chairman  
Panchayat Samiti, Nuapada

Countersignature

*K. S. 5/5/22*  
Collector  
Nuapada

*K. S. 5/5/22*  
R.I. Farhad.

**Embankment Inspection Report of Sundar Irrigation Sub-Division (Nuapada District)**

Sl. No.	River	Name of the Embankment	Length of Embankment	Inspecting Officers		Date	Remarks
				Inspecting Officers from Block, Tahasil, Sarpanch & Irrigation Office.	Tahasil		
1	Arjun Jharia Nallah	Thongo Embankment (Embankment near village Thongo)	0.90 Km	Sri Tarun Kumar Nayak (AEE, Sundar Irr. Project)	Komna	04.05.2022	The embankment of Arjun Jharia Nallah near Thongo village is in good condition.
				Sri Shisir Kumar Meher (JE, Sundar Irr. Project)	Komna	04.05.2022	The embankment of Arjun Jharia Nallah near Thongo village is in good condition.
				Sri Santanu Kumar Rana (JE, Komna Block)	Komna	04.05.2022	The embankment of Arjun Jharia Nallah near Thongo village is in good condition.
				Sri Akshay Naik (RI, Michapalli)	Komna	04.05.2022	Visited the spot and found that the embankment of Arjun Jharia Nallah near Thongo village is in good condition.

*[Signature]*  
 Senior Engineer  
 Sundar Irr. Sub-Division  
 Jadamunda

*[Signature]*  
 04.05.2022  
 JE - Komna Block

*[Signature]*  
 04.05.2022  
 RI, Michapalli

*[Signature]*  
 04.05.22  
 Superintending Engineer  
 Nuapada Irrigation Division  
 Sub-Division Office  
 Jadamunda  
 Sundar Irrigation Sub-Division  
 Nuapada

COUNTERSIGNATURE


*[Signature]*  
 COLLECTOR  
 NUAPADA


C





## Embankment Inspection Report of Sundar Irrigation Sub-Division (Nuapada District)


Sl. No.	River	Name of the Embankment	Length of Embankment	Inspecting Officers		Date	Remarks
				Inspecting Officers from Block, Tahasil, Sarpanch & Irrigation Office.	Tahasil		
1	Sundar	Ichhapur embankment (Embankment near Ichhapur D/S of Spillway of Sundar I.P.)	2.00 Km	Sri Tarun Kumar Nayak (AEE, Sundar Irr. Project)	Komna	02.05.2020	The embankment near Ichhapur D/S of spillway of S.P. is in good condition.
				Sri Sourav Ranjan Pradhan (JE, Sundar Irr. Project)	Komna	02.05.2020	The embankment near Ichhapur D/S spillway is in good condition.
				Sri Santanu Kumar Rana (JE, Komna Block)	Komna	02.05.2020	The embankment near Ichhapur D/S spillway is in good condition.
				Sri Akshay Naik (RI, Michapalli)	Komna	02.05.2020	The embankment near Ichhapur D/S spillway is in good condition.

  
 S. K. Rana JE  
 Komna Block

  
 R. J. Michapalli

  
 P. Raj  
 02.05.20

  
 Collector  
 NUAPADA

  
 Superintending Engineer  
 Nuapada Irrigation Division  
 Nuapada

COUNTER SIGNATURE  
 Sub-Divisional Office  
 Sundar Irrigation Sub-Division  
 Jadamunda

**INFORMATION REGARDING EXISTING RIVER / SALINE EMBANKMENT OF NUAPADA IRRIGATION DIVISION, NUAPADA.**

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Type & Length of Embankments (in Km.)			Remarks	
								CE	OAE	TRE		
1	2	3	4	5	6	7	8	9	10	11	12	13
1	Mahanadi	(Un named Tributary of Ong) Saipala Nallah	Nuapada / Bargarh	Nuapada / Paikmal	Nuapada / Padmapur	L/R	Pipalehhendei embankment (Embankment near village Pipalchhendei in D/S of Spillway of Saipala Irrigation Project.		1.10			
							<b>Total</b>		<b>1.10</b>			

I have visited the river embankment covering 100% length and there is no vulnerable points noticed.

*D. Jha*  
30/1/22  
Junior Engineer

I have visited the river embankment covering 100% length and there is no vulnerable points noticed.

*B. B. B. B.*  
30/1/22  
Sub-Divisional Officer  
Mandosil Irr. Sub-Division  
Mandosil

I have visited the river embankment covering 100% length and there is no vulnerable points noticed.

*[Signature]*  
29/1/22  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada.



Embankment Inspection of Nuapada Irrigation Division, Date:-05.2022 as pe EE, Nuapada Irrigation Division Lr. No:-983, (WE), (3), dtd-25.04.2022.

Sl. No	Basin	River	District	Block / Tahasil	Constituency	Left / Right	Name of the Embankment	Observation
1	Mahanadi	(Un named Tributary of Ong) Saipala Nallah	Nuapada / Bargarh	Nuapada / Paikmal	Nuapada / Padmapur	L/R	Pipalchhendi embankment near village of Pipalchhendi in D/S of Spillway of Saipala Irrigation Project.	After field visit by the team it is observed that the total existing river embankment is in good condition. There is no vulnerable point noticed.

*P. Jaiswal*  
04/05/2022

Junior Engineer  
Mandosil Irrigation Sub-Division  
Saipala.

*Priyanka Saha*  
SARPANCH  
SAIPALA GRAMPANCHAYAT

*R. Jaiswal*  
04/05/2022

*P. Jaiswal*  
04/05/2022

Sub-Divisional Officer  
Mandosil Irrigation Sub-Division  
Mandosil

*P. Jaiswal*  
04.05.2022  
B.P.O. Nuapada  
Development Officer  
Nuapada

*P. Jaiswal*  
04/05/22

Superintending Engineer  
Nuapada Irrigation Division  
Nuapada.

*P. Jaiswal*  
Tahasildar, Nuapada

*P. Jaiswal*  
04.5.22  
Tahasildar, Paikmal

**TAHASILDAR  
PAIKMAL**

*Om Prakash Nayak*  
Mandosil G.P. Sarpanch

*P. Jaiswal*  
04/05/2022  
Revenue Inspector  
Darlimunda

COUNTERSIGNATURE

*P. Jaiswal*  
Padmabati Majhi  
SARPANCH  
KHAIRANI G.P.

*P. Jaiswal*  
COLLECTOR  
NUAPADA