

**Embankment Inspection of Nuapada Irrigation Division, as per Lr.No.10527 dt. 17.04.2023 of Engineer-in-Chief,  
W.R., Odisha, Bhubaneswar & S.E, Nuapada Irrigation Division Lr.No.1065 (WE) dt. 12.05.2023**

Sl. No.	Basin	River	District	Block	Constituency	Left / Right	Name of the embankment	Observation
1	Mahanadi	Kharkhara Nallah	Nuapada	Nuapada	Nuapada	R	Sida Embankment (Embankment near village Sida)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.
2	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	R	Embankment over Jonk river (Embankment near village Kurumunda)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
18/05/2023  
Junior Engineer  
Jonk Irrigation Sub-Division  
Nuapada.

*[Signature]*  
18/05/2023  
Sub-Divisional Officer  
Jonk Irrigation Sub-Division  
Nuapada.

*[Signature]*  
18.5.2023  
BLOCK DEVELOPMENT OFFICER  
NUAPADA

*[Signature]*  
18.05.2023  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada

*[Signature]*  
18/5/23  
Revenue Inspector  
Sarabong

*[Signature]*  
18.05.2023  
Asst. Executive Engineer  
Panchayat Samiti, Nuapada

*[Signature]*  
18/5/23  
TANASILDAR  
NUAPADA

*[Signature]*  
22/05/23  
Addl. Chief Engineer  
Western Irrigation Circle  
Bhawanipatna

*[Signature]*  
COLLECTOR  
NUAPADA

**Embankment Inspection of Nuapada Irrigation Division, as per Lr.No.10527 dt. 17.04.2023 of Engineer-in-Chief,  
W.R., Odisha, Bhubaneswar & S.E, Nuapada Irrigation Division Lr.No.1065 (WE) dt. 12.05.2023**

Sl. No.	Basin	River	District	Block	Constituency	Left / Right	Name of the embankment	Observation
1	Mahanadi	Kharakhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Kalyanpur Embankment (Embankment near village Kalyanpur & U/S of Kharakhara barrage)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.
2	Mahanadi	Kharakhara Nallah	Nuapada	Nuapada	Nuapada	L	Chanabeda Embankment (Embankment near village Chanabeda in D/S of Kharakhara barrage)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.
3	Mahanadi	Kharakhara Nallah	Nuapada	Nuapada	Nuapada	L/R	Mahatamtora Embankment (Embankment near village Mahatamtora of Kharakhara nallah)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*F. G. Chandra*  
17.5.23

*W. S. S. S. S.*  
17/05/2023

Junior Engineer  
Jonk Irrigation Sub-Division  
Nuapada.  
Junior Engineer  
Jonk Irrigation Sub-Division  
Nuapada.

Sub-Divisional Officer  
Jonk Irrigation Sub-Division  
Nuapada.

*P. S. S. S.*  
13-5-24  
Revenue Inspector  
Parkod

*S. S. S. S.*  
18.05.2023  
Regional Engineer  
Kharakhara Road

*S. S. S. S.*  
18.05.2023  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada

*S. S. S. S.*  
17.5.2023  
BLOCK DEVELOPMENT OFFICER  
NUAPADA

Asst. Executive Engineer  
Panchayat Samiti, Nuapada

*S. S. S. S.*  
12/5/23  
TAHASILDAR  
NUAPADA

*S. S. S. S.*  
COLLECTOR  
NUAPADA

*S. S. S. S.*  
22/05/23  
Addl. Chief Engineer  
Western Irrigation Circle  
Bhawanipatna

Embankment Inspection of Nuapada Irrigation Division, dt-16.05.2023 as per Lr.No.10522 dt. 17.04.2023 of Engineer-in-Chief, W.R., Odisha, Bhubaneswar & SE, Nuapada Irrigation Division Lr.No.1065(W/E) dt. 12.05.2023

Sl. No	Basin	River	District	Block/ Tahasil	Constituency	Left / Right	Length OAE	Name of the embankment	Observation
1	2	3	4	5	6	7	8	9	10
1	Mahanadi	Un-named tributary of Ong	Nuapada	Nuapada	Nuapada	L/R	1.10	Pipalchandi Embankment (Embankment near village-Pipalchandi in D/S of spillway of Saipala Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
 Revenue Inspector  
 Darftranda  
 Darftranda

*[Signature]*  
 Assistant Engineer  
 Mandosil Irrigation Sub-Division  
 Mandosil.

*[Signature]*  
 Sub-Divisional Officer  
 Mandosil Irrigation Sub-Division  
 Mandosil

*[Signature]*  
 Superintending Engineer  
 Nuapada Irrigation Division  
 Nuapada.

*[Signature]*  
 Sarpaach  
 Sarpaach Gram Panchayat

*[Signature]*  
 Sarpaach  
 KHAIRANI G.P.

*[Signature]*  
 Asst. Executive Engineer  
 Panchayat Samiti, Nuapada

*[Signature]*  
 Tahasildar  
 TAHASILDAR  
 NUAPADA

*[Signature]*  
 Block Development Officer  
 BLOCK DEVELOPMENT OFFICER  
 NUAPADA

*[Signature]*  
 COLLECTOR  
 NUAPADA

*[Signature]*  
 Addl. Chief Engineer  
 Western Irrigation Circle  
 Bhawanipatna

# Embankment Inspection Report of Sundar Irrigation Sub-Division (Nuapada District)

SR

Sl. No.	River	Name of the Embankment	Length of Embankment	Inspecting Officers		Date	Remarks
				Inspecting officers from Block, Tahasil, Gram Panchayat & Irrigation Office	Tahasil		
1	Sundar	Ichhapur Embankment (Embankment near Ichhapur D/S of Spillway of Sundar Irrigation Project)	2.00 Km	Sri Tarun Kumar Nayak (AEE, Sundar Irr. Project)	Komma	16.05.2023	The embankment is in good condition.
				Sri Shisir Kumar Meher (AE, Sundar Irr. Project)	Komma	16.05.2023	Embankment is in good condition
				Akshay Ku. Mahapatra (G.E, Komma Block)	Komma	16.05.2023	Embankment is in good condition
				Rajyanshu Sharma (R.I. Wickhopali)	Komma	16.05.2023	Embankment is in good condition

*P. Krishna*  
*Saravananth P.*  
*Jadamunda, Komma*  
 16.05.2023  
 Asst. Engineer  
 Sundar Irr. Sub-Division  
 Jadamunda, Komma

*Prasanna*  
 16.05.2023  
 Asst. Engineer  
 Sundar Irr. Sub-Division  
 Jadamunda, Komma

*Prasanna*  
 16.05.2023  
 Asst. Eng. Engineer  
 Sundar Irr. Sub-Division  
 Jadamunda, Komma

*Rev. Inspector*  
 Revenue Department  
 Nuapada

**Embankment Inspection Report of Sundar Irrigation Sub-Division (Nuapada District)**

16

16

Sl. No.	River	Name of the Embankment	Length of Embankment	Inspecting Officers		Date	Remarks
				Inspecting officers from Block, Tahasil, Gram Panchayat & Irrigation Office	Tahasil		
2	Ajun Jharla Nallah	Thongo Embankment (Embankment near Thongo village of Sundar Irrigation Project)	0.90 Km	Sri Tarun Kumar Nayak (AEE, Sundar Irr. Project)	Komma	16.05.2023	The embankment is in good condition.
				Sri Shisir Kumar Meher (AE, Sundar Irr. Project)	Komma	16.05.2023	Embankment is in good condition
				Akshay Ku. Mohapatra G.E. Komma Block	Komma	16.05.2023	Embankment is in good condition
				Reshama Lal Sharma (P. I. Wickhopali)	Komma	16.05.2023	Embankment is in good condition.

*Reshma Lal Sharma*  
*Reshma Lal Sharma*  
 Addl. Chief Engineer, Komma Block  
 Western Irrigation Circle  
 Bhawanipatna

*Chaitanya Kumar*  
 Chief Engineer, Project  
 Bundar, Sub-Division  
 Nuapada

*Chaitanya Kumar*  
 Asst. Exp. Engineer  
 Bundar Irr. Sub-Division  
 Nuapada

*Chaitanya Kumar*  
 District Member  
 Nuapada

*Chaitanya Kumar*  
 Revenue Officer  
 Nuapada

*Chaitanya Kumar*  
 Superintending Engineer  
 Nuapada Irr. Divn, Nuapada.

**Embankment Inspection of Nuapada Irrigation Division, dt-16.05.2023 as per Lr.No.10522 dt. 17.04.2023 of Engineer-in-Chief, W.R., Odisha, Bhubaneswar & SE, Nuapada Irrigation Division Lr.No.1065(WE) dt. 12.05.2023**

Sl No	Basin	River	District	Block/ Tahasil	Constituency	Left / Right	Lenh OAE	Name of the embankment	Observation
1	Mahanadi	Jonk	Nuapada	Nuapada	Nuapada	L/R	0.80	Patara Embankment (Embankment near village-Patora in D/S of spillway of Upper Jonk Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
 Revenue Inspector,  
 Dharambandha G.P.  
 Dharambandha  
 Sarabong

*[Signature]*  
 Assistant Engineer  
 Jonk Irrigation Sub-Division  
 Nuapada

*[Signature]*  
 Sub-Divisional Officer  
 Jonk Irrigation Sub-Division  
 Nuapada

*[Signature]*  
 Superintending Engineer  
 Nuapada Irrigation Division  
 Nuapada.

*[Signature]*  
 Revenue Inspector,  
 Sarabong

*[Signature]*  
 Sarpanch Wera G.P.  
 Khutban Ehera G.P.

*[Signature]*  
 Sarpanch Dharambandha G.P.  
 Dharambandha G.P.

*[Signature]*  
 Asst. Executive Engineer  
 Panchayat Samiti, Nuapada

*[Signature]*  
 Addl. Chief Engineer  
 Western Irrigation Circle  
 Bhawanipatna

*[Signature]*

**COLLECTOR  
 NUAPADA**

*[Signature]*  
 Tahasildar  
 Nuapada.

*[Signature]*  
 Block Development Officer  
 Nuapada

**Embankment Inspection of Nuapada Irrigation Division as per Lr.No.10527 dt.17.04.2023 of Engineer-in-Chief, W.R., Odisha,  
Bhubaneswar & S.E, Nuapada Irrigation Division Lr.No.1065(3)(WE) dt.12.05.2023**

Sl. No	Basin	River	District	Block/Tahasil	Constituency	Left / Right	Name of the embankment	Observation
1	Mahanadi	Kokrijhore	Bargarh	Jharbandh	Padampur	LR	Kotna embankment (Embankment near village Kotna in D/S of spillway of Jharbandha Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.
2	Mahanadi	Ong	Bargarh	Jharbandha	Padampur	LR	Lergaon embankment (Embankment of river Ong near village Lergaon)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*[Signature]*  
14/5/2023  
Asst. Engineer  
Mandasil Ir. Sub-Division  
Mandasil

*[Signature]*  
16/05/2023  
Sub-Divisional Officer  
Mandasil Ir. Sub-Division  
Mandasil

*[Signature]*  
18.05.2023  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada

*[Signature]*  
15/5/2023  
Revenue Inspector  
Lanipatna

*[Signature]*  
12/5/23  
Assistant Engineer  
Jharbandh

*[Signature]*  
16/05/2023  
A.E.D.O.  
Jharbandh

*[Signature]*  
18/5/23  
REVENUE INSPECTOR  
JHARBANDH

*[Signature]*  
18/5/23  
Revenue Inspector  
Lanipatna

*[Signature]*  
18/5/23  
Sarapanch  
Jharbandh Q.P

*[Signature]*  
Collector  
BARGARH

*[Signature]*  
22/05/23  
Addl. Chief Engineer  
Western Irrigation Circle,  
Bhawani Patna

**Embankment Inspection of Nuapada Irrigation Division as per Lr.No.10527 dt.17.04.2023 of Engineer-in-Chief, W.R., Odisha,  
Bhubaneswar & S.E, Nuapada Irrigation Division Lr.No.1065 (WE) dt.12.05.2023**

Sl. No	Basin	River	District	Block/ Tahasil	Confluence	Left / Right	Name of the embankment	Observation
1	2	3	4	5	0	7	0	0
1	Mahanadi	Un-named tributary of Ong	Bargarh	Palkmal	Padampur	L/R	Bhutmunda Embankment (Embankment near village Bhutmunda D/S of splitway of Dumerbahal Irrigation Project)	After field visit by the team it is observed that total existing river embankment is in good condition. There is no vulnerable point noticed.

*Ri*  
14.05.23  
Asst. Engineer  
Mandosil Ir. Sub-Division  
Mandosil

*Wahidullah*  
14.05.2023  
Sub-Divisional Officer  
Mandol Ir. Sub-Division  
Mandol

*Dumra*  
17.05.2023  
Superintending Engineer  
Nuapada Irrigation Division  
Nuapada

*Abal*  
14.05.23  
Revenue Officer  
Mandosil

*Om Prakash Nanda*  
Satrapach  
Mandosil G.P

*W*  
14.05.23  
Tahaashdar  
Palkmal

*Parrot*  
14/5/23  
Block Development Officer  
Palkmal

*Agar*  
COLLECTOR  
BAIRGARH

Addl. Chief Engineer  
Western Irrigation Circle  
Bhawaniapatna



OFFICE OF THE ADDITIONAL CHIEF ENGINEER  
WESTERN IRRIGATION CIRCLE, BHAWANIPATNA  
Phone No.06670-230763/ Email-sewic2012@gmail.com

\*\*\*\*\*

No. 1554 /Date. 31.05.2023

To  
The Chief Engineer HH, GIS & CEM,  
Bhubaneswar.

Sub: Submission of embankment verification report and vulnerable reaches regarding preparedness of possible flood during monsoon 2023.

Sir,


In inviting a kind reference to the letter and subject cited above, the physical verification of embankment reports of Kalahandi Irrigation Division, Bhawanipatna and Nuapada Irrigation Division, Nuapada duly countersign by the respective Collector & District Magistrates and the Addl. Chief Engineer, Western Irrigation Circle, Bhawanipatna are submitted for favour of your kind information and necessary action.

It is to mention that there is no vulnerable point of the embankments under this Circle.

This is for your information and necessary action.

Encl:- Inspection Report of Embankments of  
N.I.D - 8 pages  
K.I.D - 3 pages

Yours faithfully,

  
Additional Chief Engineer  
Western Irrigation Circle  
Bhawanipatna

Memo No. 1555 /Date. 31.05.2023  
Copy submitted to the Engineer-in-Chief, Water Resources, Odisha, Bhubaneswar for favour of kind information and necessary action with reference to his Circular Memo No.10526 dtd.17.04.2023.

  
ADDITIONAL CHIEF ENGINEER

Memo No. 1556 /Date.31.05.2023  
Copy submitted to the Chief Engineer & Basin Manager, Tel Basin, Bhawanipatna for favour of kind information and necessary action with reference to his Memo No.1272 dtd.20.04.2023.

  
ADDITIONAL CHIEF ENGINEER

Memo No. 1557 /Date 31.05.2023  
Copy forwarded to the Superintending Engineer, Kalahandi Irrigation Division, Bhawanipatna & Superintending Engineer, Nuapada Irrigation Division, Nuapada for information and necessary action with reference to his Memo No.1249 (WE) dtd.10.05.2023 and Lr No.1150(WE) dtd.29.05.2023.

  
ADDITIONAL CHIEF ENGINEER